Management Planner: _

RE-INSPECTION

An Asbestos Hazard Emergency Response Act (Inspection was conducted in the following building per the requirements of Environmental Protection Regulations (CFR) Part 763(b):	gs of the Hanover Area	School District
Hanover Green Elementary School	Memorial Elementa	ary School
Hanover Area Junior/Senior High School	Lee Park Elementa	ry School
Field House at Memorial Elementary and Fie	eld House	
☑ Garage at Junior/Senior High School and Ga	rage	·
A visual inspection was conducted in all areas of AHERA Management Plan as containing commaterials (ACBM) or assumed ACBM. There (we in the condition of confirmed or assumed ACB periodic surveillance/re-inspection data; there renovations; and there (were as noted below) (we functional space(s) that could potentially damage notifications and any/all other AHERA related do 763.94 are included as an update to each of the builded ARE:	offirmed asbestos containere as noted below) (we make the mass of	ining building by the most recent (were no) ilization of the mation and all 4 40 CFR part ement Plans.
Designated Person: Warpe & Thomas	Date: _	10/27/21
Inspector: Fell (1)	Date: _	10/27/21
Wayne D. From a	٠.	

#001581 Date: 10/27/21

PERIODIC SURVEILLANCE

An Asbestos Hazard Emergency Response Act (A surveillance was conducted in the following but District per the requirements of Environmental Procedural Regulations (CFR) Part 763(b):	ildings of the Hanover Area School		
Hanover Green Elementary School	Memorial Elementary School		
Hanovér Area Junior/Senior High School	Lynwood Elementary School		
Field House at Memorial Elementary	Lee Park Elementary School		
☐ Garage at Junior/Senior High School	,		
A periodic surveillance was conducted in all areas of the building(s) that are identified in the AHERA Management Plan as containing confirmed asbestos containing building materials (ACBM) or assumed ACBM. There (were as noted below) / (were no) changes in the condition of confirmed or assumed ACBM as compared with the most recent periodic surveillance/re-inspection data; there (were as noted below) / (were no) renovations; and there (were as noted below) / (were no) changes in the utilization of the functional space(s) that could potentially damage the ACBM. This information and all notifications and any/all other AHERA related documentation per USEPA 40 CFR part 763.94 are included as an update to each of the building(s) AHERA Management Plans. NOTED CHANGES SINCE LAST PERIODIC SURVELLIANCE/REINSPECTION ARE:			
·			
Designated Person:	Date: <u>4/6/2/</u>		
Inspector: Emment forto	Date: 4/9/21		
Management Planner: #00	1581 Date: 4/9/2/		